
Measuring Guide

This document is to help instruct you on how to take accurate measurements for your radiation protection garment.



Key Measurements

Chest (C).

The chest should be measured around the fullest part of the chest.

Waist (W).

Circumference of waist at bully button level.

Hips (H).

The hips should be measured around the fullest part of the body.

Top Length (TL).

Measured at the front of the body, from center of the shoulder to the hem of vest. The finished length should allow a minimum of 10 cm overlap (vest and kilt overlap).

Kilt length (KL).

Measured from the top of the kilt to the knee.

Total length (L). This should be measured from center shoulder on the front of the body to the hem of the apron or to the knee.

	Extra small	Small	Medium	Large	Extra large
To fit chest up to (C)	82cm	9 2cm	l02cm	l12cm	I22cm
To fit waist up to (W)	71cm	81cm	91cm	101cm	lllcm
To fit hips up to (H)	87cm	97cm	107cm	II7cm	I27cm

Lengths	Short	Regular	Long	X - long
I piece Apron (L)	82cm	9 2cm	I02cm	l I 2cm
2 piece Apron (KL/TL)	51cm	56cm	61cm	66 cm



For further guidance please watch the Burlington Medical tutorial on how to measure: <u>https://www.youtube.com/watch?v=NmZ5_04hgRM</u>

If you need any further assistance please contact your local account manager or sales@protecx.co.uk